

Schedule of Watercourse Clearance and Repair - April 2018-2019

Location	Watercourse	Description of Works	Completion / Expected Completion Date
Scottish Borders	All Watercourses	Debris Clearance	Removal of Debris if considered flood risk
Scottish Borders	All Reservoirs	General Reservoir Maintenance	Annually
Ettrick Valley	Tima Water	Study to inform remedial works	Summer 2018 - March 2019
Galashiels	Gala Water	Tree Removal - Near Sykes	May-18
Selkirk	Ettrick Water	Tree Removal	May-18
Innerleithen	Leithen Water	Tree Removal	May-18
Yetholm	Bowmont Water	Tree Removal	Jun-18
Galashiels	N/A	Sandbag Store Repair	Jun-18
Hawick	Slitrig Water	Wall Repair	Jul-18
Galashiels	Gala Water	Wall Repair	Jul-18
Galashiels	Mill Lade	Silt Removal / Clearance	Jul-18
Newtown St Boswells	Glen Burn	Vegetation Clearance	Aug-18
Broughton	N/A	Renew Sandbag Store	Aug-18
Galashiels	Bakehouse Burn	Trash Screen Replacement and Improvements	Sep-18
Jedburgh	Jed Water	River Wall Repair Works	Sep-18
Hawick	River Teviot	Flood Gate Repair Works	Sep-18
Clovenfords	Surface Water Run Off	Drainage Investigation	Nov-18
Jedburgh	Jed Water	Flood Gate Repair Works	Dec-18
Denholm	Un-named Burn	Grille Improvements	Dec-18
Peebles	Edderston Burn / River Tweed	Culvert Clearance	Dec-18
Jedburgh	Jed Water	Tree Removal	Dec-18